



TXD 008016.3166

1411 East Luffkin Ave

Lufkin (Angolina)

Texas

75901

DATE

See Attached Sheet

G. IF AN ENFORCEMENT CASE HAS BEEN FILED, SPECIFY THE DATE FILED (mo., day, & yr.).

David Gonzalez: (.64-ES)

2. DATE (mo., day, & yr.)

12141 • 655-6740

01/27/88.

2

1

19

9

1

1

5

2

9649362



SUPERFUND FILE

~~NOV 13 1992~~

REORGANIZED

2

bec: 6E-FF

Lufkin Creosoting (TXD008063651)
Final Strategy Determination
03/27/88

Rationale for Disposition

The Lufkin Creosoting site is an inactive wood treating facility which has undergone limited remedial action under RCRA authority (TWC). The remedial action consisted of removing several tanks containing creosote sludge. However, analysis of samples taken by Engineering Science, Inc. after the removal action was complete identified moderate levels of several constituents of creosote. Information provided by the site inspection report and the TDH indicate that there are not any surface water or groundwater receptors within a 3 mile radius of this site. For this reason, this site is not considered a candidate for the NPL and no further investigative action is necessary under federal authority.

SUPERFUND FILE

NOV 13 1992

REORGANIZED